



# AI-12C Indicator



## Specifications

<b>A/D conversion speed</b>	10 times/second
<b>10 times/second</b>	-3.9 to 3.9mV/V (Bi-polar)
<b>Input sensitivity</b>	≥ 0.5μ V/e
<b>Load Cell Excitation</b>	DC 5V; I ≤ 150 mA
<b>Maximum Connection No. of Load Cells</b>	8 * 350 Ω load cells/ 16* 700 Ω load cells
<b>Load Cell Connection Method</b>	4-wire, 5V excitation
<b>Maximum Display Divisions</b>	-30000 to 30000 (60000d)
<b>Maximum internal counts</b>	-500000 to +500000
<b>Divisions (Optional)</b>	1/2/5/10/20/50
<b>Size</b>	245mm*178mm* 95mm
<b>Power Supply</b>	230V Mains

- Bright 40mm (1.6") high LCD Display
- Animal weighing mode
- Peak Hold facility (for positive signal)
- Rechargeable 6V/4AH SLA battery
- Zero and Tare Keys
- Max to +Max capacity display
- Configurable Function (F) key
- Kg / lb / kN units
- RS232 PC / Printer port: Optional
- 6 Keys Key pad (Membrane keyboard)