

BWS Stainless Steel Indicator



Specifications

A/D conversion speed	10 times/second
Input signal range	0 to 3.5mV/V
Input sensitivity	$\geq 0.5\mu\text{V/e}$
Load cell excitation	DC 5V; $I \leq 150\text{ mA}$
Maximum connection number of load cells	4 * 350 Ω load cells/ 8* 700 Ω load cells
Load cell connection method	4-wire
Maximum display divisions	30,000
Maximum internal counts	200,000
Divisions (optional)	1/2/5/10/20/50
Display	6-digits LCD (51mm high)
Power supply	230V Mains with 12V power adapter

Features

- Bright LCD Display
- Animal weighing mode
- Stainless Steel casing (IP66)
- Rechargeable 6V/4AH SLA battery
- Zero and Tare Keys
- 51mm digit display
- Check weighing
- Parts counting
- 6 Keys Key pad
- RS232 PC/Printer port: Optional